

- Switch the light off before charging
- 2 Plug the USB cable into the USB-C input and connect to an appropriate adapter/power source
- 3 The battery indicator will flash the corresponding battery level when charging When the battery has finished charging all lights will be solid blue
- 4 Charging time is approximately 4 hours

MAINTENANCE:

- A full charge of at least 4 hours prior to initial use is recommended
- 2 Always recharge after use
- It is advisable to charge the battery if not used for 3 months

CAUTION:

- Never attempt to disassemble the inspection light
 Never shine the inspection light directly in someone's eyes
 Do not over rotate the inspection light
- 3 joint, Maximum rotation 180°

INSTRUCTIONS FOR USE:

COB Inspection Light 400Im	
RUNNING TIME (Approx)	Inspection Light: 3 hours Red Light: 3 hours Flashlight: 5 hours Tip Light: 17 hours
CHARGE TIME	4 Hours at 1A
BATTERY TYPE	3.7V 2600mAh lithium battery
CHARGE INPUT	5V 1A
OUTPUT	5V 1A
4 OPERATION MODES	Inspection Light> Red light > Tip light > Front flashlight All modes are dimmable
LUMENS	Up to 400 lumens
IP LEVEL	IPXO
IK LEVEL	IK07

Press the power button / mode switch to turn Hold power button on any mode to adjust 3 brightness, once max/min brightness is the inspection light ON, the battery indicator will achieved the light will blink. light up the corresponding battery level. Further presses of the power button/mode Located on the base of the product is the; switch will change between modes: magnet, hanging hook, and the clamp. 2 a. Inspection light / b. Red light / c. Tip light. Pull the hanging hook down to operate the Double tap for flashlight. clamp.

Carl Kammerling International Ltd, Pwllheli, LLS3 5LH, United Kingdom Carl Kämmerling GmbH & Co. KG, Bendahler Str. 110. 42285 Wuppertal. Germany

Ð