## User Guide (v1.0)

LED head torch 220lm

Please read the following instructions carefully and keep for future reference. Correct usage and maintenance are essential to ensure maximum battery life and performance.

Box Contents:
• **1 x** Head torch
• **1 x** Instruction manual

Light control button   Sensor ON/OFF button

Red Light
Main light SW CREE XTE
Sensor
Battery holder

COB LED

CAUTION:

1	Never attempt to disassemble the head torch
2	Never shine the torch directly in someone's eyes

INSTRUCTIONS FOR USE:

1	Press the power button / mode switch to turn the site light ON.
2	Further presses of the power button/mode switch will change between modes: Full beam/Dimmed mode/red light/COB/COB+Full/COB+Dimmed/COB+Red light
3	Pressing the power button / mode switch for two seconds will turn the COB light ON and OFF
4	Pressing the sensor button activates the sensor and the light modes can by cycled through by waving a hand in front of the light
5	Pressing the sensor button for two seconds will activate the battery indicator.

LED Head Torch 220lm	
RUNNING TIME	Full beam: 4 hours Dimmed mode: 9 hours Red beam: 5 hours COB light: 9 hours COB + full beam: 135 minutes
7 OPERATION MODES	Full beam/Dimmed mode/red light/COB/COB+Full/COB+Dimmed/COB+Red light
LUMENS	up to 220 lumens
IP LEVEL	IPX4
IK LEVEL	IK05